

Biofilm Absence Accreditation

www.natureworks.es



CUSTOMER DATA	
NAME	Nature Works Tecnologías S.L.
ADDRESS	Pol. Ind. Tecnol. De Caudete, s/n
CITY	02660 Caudete (Albacete)
DELIVERY TYPE	PDF document
COMPANY NUMBER	B-03400033
REPORT SENT TO	Camacho Recycling, S.L.
AT THE ATTENTION OF	D. Francisco Camarasa Bordallo
CONTROL REQUEST	Microbiology in Swimming Pool
SAMPLE TYPE	Surfaces
E-MAIL	delfina@camachorecycling.com

SAMPLE DATA	
INSTALLATION NAME	Polideportivo Alfas del Sol
TYPE OF INSTALLATION	Public Swimming Pool
ADDRESS	C/Mislata, 4
CITY	03580 Alfas del Pi (Alicante)
COLLECTED BY	MicroAmbiente, S.L.
TECHNICIAN / HOUR	Irene Zamora / 17:30
SAMPLE DATE	Wednesday, 7th July 2010
RECEIPT DATE	Wednesday, 7th July 2010
START DATE	Wednesday, 7th July 2010
END DATE	Friday, 9th July 2010

Surface Analysis

✓ Good Sample

✗ Bad Sample

PARAMETER	METHOD	RESULT	UNITS
Mesophilic aerobics at 37°	MB-AG-01	> 300	CFU / cm ²

PARAMETER	METHOD	RESULT	UNITS
Mesophilic aerobics at 37°	MB-AG-01	490	CFU / g.

RESULT OF THE PRESENCE OF BIOFILM

- ✓ In view of the results of the visual and microbiological analysis carried out in the filter both of the filter walls and of the filtering media to determine the presence of Biofilm, we have to express that no growth of bacteria biomass (Biofilm) is observed.

viernes, 09 de julio de 2010

Laboratorio Certificado
 Certificado ISO 9001 N° 501/2005
 Certificado ISO 14001 N° 058/2005



Fdo. Verónica Castelló
 Bióloga
 Technical director of laboratory
 Microambiente S.L.

This certificate is an unauthenticated translation and has no legal validity. Please contact Nature Works Tecnologías S.L. to obtain a copy of the original report.